

ALTIMATE ENVIROCARE TREATMENT OF NTUC PASIR RIS WALKWAY SHELTER



THE STEEL COLUMNS SHOULD BE TREATED WITH ENVIROCARE PRODUCT FOR CLEANER AND LESS UNSIGHTLY SURFACE AREA



↑ WALKWAY SHELTER COVER REQUIRES TOUCHING UP AT CERTAIN AREAS THROUGHOUT SHELTER AREA

↓ ROUND STEEL COLUMNS BECOME EASILY DIRTY DUE TO SUPER-HYDROPHILIC EFFECT OF SHELTERED AREA CAUSING MOST DIRT TO FLOW OFF TREATED SURFACE AND STAIN STEEL COLUMN IN A SHORT DURATION. ALSO NOTE SUPER-HYDROPHILIC SURFACE AFTER RAINFALL

