

**ALTIMATE ENVIROCARE
EXTERIOR SURFACES TREATMENT OF CHANGI GENERAL HOSPITAL**



↑↓ BUILDING EXTERIOR ABOVE HOSPITAL EMERGENCY ENTRANCE CLEARLY SHOW BADLY STAINED CLADDING AND GLASS WINDOWS EVENTHOUGH UNDER SHELTER



AFTER TREATMENT WITH THE ENVIROCARE M7 TI02 PHOTO-COMPOUND ON GLASS AND CLADDING FOR ANTI-FUNGAL AND DECOMPOSITION EFFECT ↑↓

